

Serial No. 10/801,565

Docket No. IK-0084

Reply to Office Action of September 21, 2006

Amendments to the Specification:

Please replace the paragraph beginning at line 20 on page 13 with the following amended paragraph:

That is, as shown in detail in FIG. 4, when the freezing compartment door 84 stands upright, the left-side cover bracket 109 is located on the left of the vertical section 104b of the left-side support frame 104, and the right-side cover bracket 109' is located on the right of ~~104b~~ 104b' of the right-side support frame 104'.